Tech Info Library

Macintosh 128K/512K: DB-9 Serial Loopback Pinouts (9/95)

Article Created: 22 September 1995

TOPIC ---

What are the pinouts for the DB-9 serial loopback plug for the Macintosh 128K
and 512K computers?

DISCUSSION --

The DB-9 serial loopback (part number 077-8129) is part of the diagnostics kit
available from Apple. It can also be ordered separately under part number
077-8129

The loopback plug consists of a male DB-9 connector with pins 4 and 8 tied
together and 5 and 9 tied together using a small piece of wire-wrap wire.

The pins on the male end of the DB-9 connector are numbered as shown:

Begin_Graphic

```
        1 2 3 4 5
         6 7 8 9
```

End_Graphic

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: hts,cnfg,cabinfo

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18636