PATHWORKS 1.1: Printing to LaserWriter from a Macintosh

Article Created: 20 April 1992

```
    * RESTRICTED: Apple Internal and Support Providers Only *
                  Not For General Public Release
```

TOPIC ---

I've recently upgraded our VAX to PATHWORKS 1.1. We tested all the
features, and it ran flawlessly, except for printing to the LaserWriter IIg
on Ethernet. If I log on to the VAX and print an ASCII file, it works
fine. But if I try to print from the Macintosh, I get an error or
incompatible LaserPrep version.

DISCUSSION --

This happens when you aren't using LaserPrep version 71, included with
PATHWORKS 1.1 in the MSAP$DEVCTL.TLB device control text library. To
verify that it's there, do the following:

```
$ SET DEF SYS$LIBRARY:
$ LIBRARY/LIST MSAP$DEVCTL.TLB MSAP*
```

Look for two files: MSAP$APPLEDICT71, AND MSAP$APPLEDICT71_QUERY. If they
aren't there, check your PATHWORKS 1.1 installation.

Next, you need to include the /SETUP qualifier with the printer definition.
Follow this example:

```
$ ADMIN/MSA
MSA$MANGER> ADD PRINTER "My Printer" -
/QUEUE=SYS$PRINT -
/DESTINATION="My Printer@My Zone" -
/SETUP=MSAP$APPLEDICT71
MSA$MANAGER>START PRINTER "My Printer"
MSA$MANAGER>EXIT
```

With the /SETUP qualifier, printing from both VAX and Macintosh computers
works fine.
Copyright 1992 Apple Computer, Inc.

Keywords: <None>

```
==================================================================
```

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10137