Tech Info Library

PowerBook 5300: Enabler v1.0.8 Crashes Minimal System (1/96)

Article Created: 15 January 1996

TOPIC ---

My computer crashes when I try to startup from a minimal System Folder on my
PowerBook 5300 Series computer. This crash occurs if the minimum System Folder I
am starting from is on either a hard drive or a RAM disk.

DISCUSSION --

This is a known issue that occurs with System 7.5.2 and PowerBook 5300 Enabler
v1.0.8. This has been fixed in PowerBook 5300/190/2300 Enabler 1.2.1 which has
been posted online as part of the PowerBook 5300 Software Update package.

These articles can help you locate the software update mentioned here:

• "Where To Find Apple Software Updates" -- Lists online services for free Apple
software updates.

• "Obtaining Apple Product Support in the USA" -- Lists 800 numbers and online
services for software updates, Apple support information, and a subset of the
Apple Tech Info Library.

Support Information Services
Copyright 1996, Apple Computer, Inc.

Keywords: kpbook

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 19210