System 7: Dialog Box When Rebuilding Desktop (9/93)

Article Created: 23 November 1992
Article Reviewed/Updated: 23 September 1993

```
    * RESTRICTED: Apple Internal and Support Providers Only *
                 Not For General Public Release
```

TOPIC ---

When I rebuild the desktop, the "mercury" in the thermometer goes past the
end and into the "STOP" button. Has this bug been fixed in System 7.1?

DISCUSSION --

No. The problem doesn't pose any harm. It's still filed as a bug.

Article Change History
----
23 September 1993 - Reviewed for technical accuracy.
8 February 1993 - Reviewed for technical accuracy.
Copyright 1992, 1993, Apple Computer, Inc.

Keywords: sys7

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11072