Pwr Mac 9500 Series: Incompatible w/ Newton Toolkit (10/95)

Article Created: 12 July 1995
Article Reviewed/Updated: 30 October 1995

TOPIC --

This article discusses compatibility between the Newton Toolkit and Power
Macintosh 9500 computers.

DISCUSSION ---

The Newton Toolkit v1.0.1 and v1.5.1 are not compatible with Power Macintosh
9500 computers. There is an updater available from online services and the
Internet which updates the Newton Toolkit to a beta version of 1.5.2. Newton
Toolkit is a Newton software development program available through Apple
Programmers and Developers Association (APDA).

In addition to the update, the latest System Enabler is needed on the Power
Macintosh 9500. This enabler can be found on v2.0 of the Power Macintosh 9500
compact disc. Open Transport v1.0.6 and later also installs the latest System
Enabler.

SYMPTOM: Error Message - "Could Not Obtain Required Resource" when opening the
Newton Toolkit Application.

SOLUTION: Updated Power Macintosh 9500 Enabler and Newton Toolkit.

SYMPTOM: Newton Toolkit Application crashes without an error.

SOLUTION: Updated Power Macintosh 9500 Enabler and Newton Toolkit.

Article Change History:
30 Oct 1995 - Added information on obtaining new version of Toolkit.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: kcompat,knmp,kppc

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18143