Apple Scanner: 8-Pin Port Is Non-Functional

```
Article Created: 14 February 1991
Article Last Reviewed:
Article Last Updated:


TOPIC -----------------------------------------------------------

I need information regarding the 8-Pin port that is next to SCSI port on
the Apple Scanner.  What is it for?  (The icon indicates LocalTalk.)  How
can developers find out more about implementing it?

DISCUSSION ------------------------------------------------------

The port was originally intended to allow the scanner to be connected to the
network.  This capability was eventually dropped, so the port is essentially
connected to nothing.  There is no way for developers to use the port.
Copyright 1991 Apple Computer, Inc.


Keywords:  <None>


==================================================================

This information is from the Apple Technical Information Library.

19960215 11:05:19.00
```

Tech Info Library Article Number: 6776