Color LaserWriter 12/600 PS: Preventing Toner on Paper (7/95)

Article Created: 6 June 1995
Article Reviewed/Updated: 19 July 1995

TOPIC ---

I have an Apple Color LaserWriter 12/600 PS, and I am getting small amounts of toner on the printed page. What can I do to prevent it?

DISCUSSION ---

Cleaning the excess toner from the following areas should eliminate the problem:

• Clean density sensor and separation discharge wire with the brush
  provided. This procedure is described on page 223 of the user's guide.

• Clean the paper pickup area as described on page 226 of the user's
  guide.

• Printing 10 blank pages will help clean toner off rollers.

This article was publised in the "Information Alley":
Volume II, Issue 5, Page 8

Article Change History:
19 Jul 1995 - Added Info Alley information; updated.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: kalley

===

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17873