Color LW 12/600 PS: Don't Bypass PageMaker Driver (8/95)

Article Created: 08 August 1995
Article Reviewed/Updated: 22 August 1995

TOPIC ---

When I bypass the PageMaker print driver, using Option-Print, PageMaker does not
seem to send the correct black color information to the color LaserWriter 12/600
PS printer. However, I get the correct black color information using the
PageMaker print driver; Print from the File menu.

Because the PageMaker driver often causes problems, I sometimes try printing
with Apple's LaserWriter driver using Option-Print. Is there a way to get the
correct colors from PageMaker using the Apple LaserWriter printer driver?

DISCUSSION --

You don't get dark blacks from PageMaker using the Option-Print because of the
way Adobe sends the information to the Apple Printer Driver. Adobe technical
support is aware of the problem, but state that using the OPT-PRINT is NOT a
supported solution. If you are encountering problems printing using PageMaker's
print command, you should contact Adobe technical support. Instead of using
Opt-Print, Adobe Technical Support will assist you in determining your printing
problem.

Article Change History:
22 Aug 1995 - Clarified the problem and solution.
18 Aug 1995 - Edited for technical accuracy.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: kcompat

===

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18390