Tech Info Library

LaserWriter IINTX: Trouble Initializing Attached Hard Drive

Article Created: 15 July 1990
Article Last Reviewed: 2 June 1992
Article Last Updated: 2 June 1992

TOPIC --

My LaserWriter IINTX is connected to an Apple 40SC Hard drive. My hard
drive's SCSI ID is set to 5 and is properly terminated. When I attempt to
to initialize the hard disk using the LaserWriter Font Utility, the
initialize button is always greyed out.

DISCUSSION ---

Be sure that you have:

• Connected the drive to the 50-pin SCSI connector instead of the DB-25
 port serial connector on the I/O board.

• Not connected your computer to the same SCSI bus as the printer and
  the hard drive.

• Let the drive become ready before turning on the LaserWriter IINTX.

If all the above are correct, you may have a bad LaserWriter IINTX
controller or hard drive mechanism.
Copyright 1991, 1992 Apple Computer, Inc.

Keywords: <None>

===

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7742