Tech Info Library

PowerBook 150: Printing Issue with German 7.5 Mac OS (3/96)

Article Created: 15 February 1996
Article Reviewed/Updated: 28 March 1996

TOPIC ---

I am having problems printing to a StyleWriter II printer from my PowerBook 150.
The PowerBook 150 has a German localized version of System 7.5 installed on it.
When I try printing a file I get this error message:

"Es ist ein Fehler im Drucker aufgetreten. Überprüfen Sie Bitte, ob der Drucker
korrekt angeschlossen ist. Starten Sie anschließend den Druckvorgang errent."

 If I put a German localized version of System 7.1.1 on the PowerBook it works
properly. Is there something wrong with the German Localized version of System
7.5?

DISCUSSION ---

This issue is related to the localized version of the StyleWriter II driver v1.2
included with the German System 7.5 software.

In order to print using a PowerBook 150 and the German version of System 7.5,
you need to use the StyleWriter 1200 v2.1.1 printer driver.

NOTE:
This issue would most likely occur on other Macintosh computers as well.

Since the German localized StyleWriter 1200 v2.1.1 printer driver is backward
compatible and included with the German System 7.5 software, you can and should
use this printer driver.

Copyright 1996, Apple Computer, Inc.

Keywords: kpbook

==

This information is from the Apple Technical Information Library.

19960329 07:17:10.00

Tech Info Library Article Number: 19351