



# Tech Info Library

## Apple II SCSI Card: ROM Upgrade (2/97)

Article Created: 14 February 1991

Article Reviewed/Updated: 28 February 1997

TOPIC -----

This article describes how to obtain the Apple II SCSI Card ROM upgrade.

DISCUSSION -----

There is a repair extension that covers your on this. Contact your dealer about getting the cards upgraded. Here is the information the dealer will need:

SCSI INTERFACE CARD IIE & IIGS ROM UPGRADE--OLC123  
(Announced March 88)

Users who upgrade to Apple IIGS Operating System Version 4.0 or greater must use the latest revisions of both the SCSI Interface Card and the ProFile Interface Card. You can determine the latest version of these interface cards by checking the part number of their ROM. As of March 88, ROM part number 341-0437, Revision A, is the latest version of the SCSI Interface Card. All SCSI and ProFile Interface Cards now shipped by Apple are the latest revisions.

Apple has revised the ROM on the Apple II SCSI Interface Card to make the card compatible with the Apple-CD SC and the Apple IIGS Operating System. When other products requiring the new ROM are introduced, you will be notified by a Service mailing. The ROM on the card can be identified by the new part number, 341-0437. All Service Stock and Finished Goods inventory has been upgraded to the new ROM.

Article Change History:

28 Feb 1997 - Reviewed for technical accuracy, revised formatting.

Copyright 1991-97, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0006781

19970303 09:51:43.00

Tech Info Library Article Number: 6781