



# Tech Info Library

## Apple IIc: Variations in keyboard ROM

Apple IIc ROMs generate characters from differing positions on the keyboard, depending on the ROM revision. Some IIc's in Dvorak mode generate the characters from the keyboard positions shown on page 6 of the IIc reference manual and other IIc's generate

Some of the earlier Apple IIc ROM's had errors that caused the keyboard discrepancy. The current and correct version of the keyboard ROM is 'D'. Page 16 of the IIc manual shows the standard Dvorak layout.  
Apple Technical Communications

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1647