



Tech Info Library

Grappler+ Card: Using w/ProDOS 1.1.1 Software (2/97)

Grappler+ Card: Using w/ProDOS 1.1.1 Software (2/97)

Article Created: 15 November 1984

Article Reviewed/Updated: 12 February 1997

TOPIC -----

This article list the revision of the Grappler+ parallel printer interface cards experiencing problems with ProDOS 1.1.1 based software.

DISCUSSION -----

Grappler+ parallel printer interface cards that have PROM rev. 3.1 or earlier do not work well with software that is ProDOS 1.1.1-based.

Article Created:

12 Feb 1997 - Reviewed for technical accuracy, revised formatting.

Copyright 1985-97, Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0000858

19970213 10:18:12.00

Tech Info Library Article Number: 858