



Tech Info Library

Apple IIGS: Sound Modification On Rev C Boards Only

This article last reviewed: 30 March 1989

The modification to the Apple IIGS sound circuit to reduce the unwanted background noises from the port was on the Revision "C" logic boards. Unfortunately, due to some parts-availability problems, there were only 34,000 Rev. "C" logic boards produced.

Production has subsequently reverted back to Rev. "B" boards. However, service stock logic boards are modified to Rev. "C" when repaired by the Apple service repair centers.

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 3699