



# Tech Info Library

## Apple II High-Speed SCSI Card: Using with GS (11/96)

Article Created: 13 August 1991

Article Reviewed/Updated: 15 November 1996

TOPIC -----

I have an Apple IIGS with a High-Speed SCSI Card but am unable to access my SCSI Hard Drive. I am using the drivers that came on the System Tools disk 5.0.2.

DISCUSSION -----

You need to install the drivers on System Tools disk 5.0.4, which should support the High Speed SCSI card. The SCSI card is also self-terminating and any external terminators should be removed.

Article Change History

15 Nov 1996 - Reviewed for technical accuracy, revised formatting.

Copyright 1991-96, Apple Computer, Inc.

Keywords: <None>

=====  
This information is from the Apple Technical Information Library.

19961122 07:37:55.00

Tech Info Library Article Number: 8762