



Tech Info Library

Enhanced Iie: What to do When Interrupts Don't Work (10/94)

Article Created: 22 July 1985

Article Reviewed/Updated: 18 October 1994

TOPIC -----

I notice that interrupts no longer function on my Enhanced Iie, is there a workaround?

DISCUSSION -----

Interrupts pass through the 80-column firmware in the Enhanced Iie, and so interrupts will not work if you have no 80-column card installed. There are three ways to solve the problem:

1. Install an 80 column-card
2. Make sure your disk contains ProDOS 1.1.1
3. If neither of the above solutions seem to work, use the BASIC command
POKE 49162,0 to fool your Iie into thinking that it contains an
80-column card.

Article Change History:

18 Oct 1994 - Reviewed for technical accuracy, revised formatting.

Support Information Services

Copyright 1985-94, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1227