



Tech Info Library

Apple IIe Hardware: Reference Manual Errata

Page 133 in Chapter 6: Switching I/O Memory, Table 6-5

READS:

SLOT CXROM	Slot ROM at \$3x00	\$C007	49159	-16377	Write
	Internal ROM at \$Cx00	\$C006	49158	-16378	Write

SHOULD READ:

SLOT CXROM	Slot ROM at \$3x00	\$C006	49158	-16378	Write
	Internal ROM at \$Cx00	\$C007	49159	-16377	Write

Apple Technical Communications

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 164