



Tech Info Library

AppleWorks: Form feed problem with some third party printers

At times, AppleWorks' Top-of-Form command does not work properly with some third party printers, including the Juki printer. If your printer seems to ignore AppleWorks' Top-of-Form command, follow this procedure:

1. Check the printer's Top-of-Page and Lines-Per-Inch settings.
2. Change AppleWorks' "Accepts Top of Page" to NO.
3. Turn off the printer.
4. Align the top of the form on the printer.
5. Turn on printer.
6. Proceed as usual.

Apple Technical Communications

Keywords: <None>

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 778