

Pinpoint: GraphMerge/IIc: superflous Z in printout

SYMPTOM:

There is a minor problem when printing multiple graphic images from an Apple IIc with an Imagewriter or Scribe. A superfluous "Z" appears in the printout preceeding the second graphic image (and each one afterwards).

USER RESPONSE:

The user should send back the disk for a free upgrade. Version 1.1 will resolve this problem.

NOTE: Apple Computer Inc. is not responsible for the contents of this article. Pinpoint Publishing

Keywords: <None>

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1668