



# Tech Info Library

## Apple IIe and IIc: Can't Use Desktop

This article last reviewed: 3 September 1987

The Desktop program, although it runs under ProDOS 8, was not designed to run on an Apple IIe or Apple IIc. If you look at the memory locations starting at 1000, you'll see:

```
1000: 18 FB 5C 04 E0 D0
```

When disassembled, they translate into

```
1000: 18          CLC
1001: FB          XCE
1002: 5C 04 E0 D0  JMP E0D004
```

This is the segment of code that the Desktop executes when it exits back to ProDOS. However, those assembly language instructions are implemented only on the Apple IIGS's 65816, not on the Apple IIe's and IIc's 6502.  
<None>

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 513