



Tech Info Library

Softcard III: Problems using .RS232, .PRINTER and CP/M

Both the .RS232 and .PRINTER drivers were designed to use the built in serial port (Port C) on the Apple III. If one configures the CP/M system such that both of these drivers are active and assigned to logical devices, the first attempt to send or receive characters causes the system to crash with an inverse S D (System Death) displayed on the console. Reboot your system to recover.

Apple Tech Notes

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 616