



Tech Info Library

DOS Compatibility Card: Does Not Support AppleCD SC Drive (2/95)

Article Created: 11 January 1995

Article Reviewed/Updated: 22 February 1995

TOPIC -----

I am having problems getting a AppleCD SC drive connected to my Power Macintosh 6100 with the DOS Compatibility Card installed to recognize DOS CD-ROM discs. The show up correctly on the Macintosh desktop, but when I try reading them O, and I cannot get DOS CD-ROM discs to read correctly in when I switch to MS-DOS.

DISCUSSION -----

You can use the AppleCD SC drive for Macintosh CD-ROM discs, but not for MS-DOS CD-ROM discs.

This problem only occurs with the AppleCD SC drive. The AppleCD SC Plus, AppleCD 150, AppleCD 300, or AppleCD 300 Plus drives work without a problem.

With the AppleCD SC drive, you can sometimes read directories, however trying to run applications from the disc results in the error message "CDR101: Not ready reading drive E, with Abort/Retry/Fail."

Article Change History:

22 Feb 1995 - Added keyword; minor updates.

Support Information Services

Copyright 1995, Apple Computer, Inc .

Keywords: kwindows,kalley

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17003