



Tech Info Library

CLW 12/600 PS: Changing Configuration w/ DOS Compat Card (10/96)

Article Created: 15 February 1996

Article Reviewed/Updated: 23 October 1996

TOPIC -----

I am trying to change the configuration of Color LaserWriter 12/600 PS printer from the DOS Compatibility Card to "Send Data In Binary". However, I get an error message that there is not enough memory to do perform this operation. I have a 16MB SIMM installed with 614K free of conventional memory. My Windows resources are 85% free according to the Program Manager. What is going on?

DISCUSSION -----

When setting up the Color LaserWriter 12/600 PS or the Color LaserWriter 12/660 PS printer to print from MS-DOS the printer is connected using LPT1.DOS. With this configuration the drivers for the Color LaserWriter 12/600 PS will not let you change the PostScript settings for the printer. To resolve this issue connect the printer to LPT1, make the appropriate changes in the PostScript section of the drivers setup. Then go back and change the connection settings to LPT1.DOS.

Article Change History:

23 Oct 1996 - Added Color LaserWriter 12/660 PS to discussion.

01 Apr 1996 - Minor typographical errors corrected.

Copyright 1996, Apple Computer, Inc.

Keywords: kwindows

=====

This information is from the Apple Technical Information Library.

19961023 16:31:12.00

Tech Info Library Article Number: 19350