



Tech Info Library

SoftWindows, ImageWriter II, Type 1 Errors When Printing (7/94)

Article Created: 19 July 1994

TOPIC -----

I have an ImageWriter II connected to my Power Macintosh modem port. I can print fine from the Macintosh environment, but whenever I try to print from within SoftWindows I get a type 1 errors part way through or at the end of the printing process, and SoftWindows quits. I have Epson LQ2500 emulation selected in the SoftWindows printer port selection under the Setup menu.

DISCUSSION -----

SoftWindows defaults to assigning com1: to the modem port. This can cause errors when printing, and often causes a type 1 error to come up. The solution recommended by Insignia is to have both com1: and com2: serial ports set to "none" within the "PC serial port" selection under the Setup menu, this will prevent the conflicts from occurring.

Support Information Services
Copyright 1994, Apple Computer, Inc.

Keywords: kppc, kwindows

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15868