



Tech Info Library

LaserWriter IINT: Not Recognized by Radius Accelerator

This article last reviewed: 17 March 1989

When using a Macintosh with the Radius accelerator card, the system fails to recognize the printer on the network, a LaserWriter IINT. This is a problem with the ROMs on the Radius accelerator card. There is no current solution.

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 3691