



Tech Info Library

Mac IIci: EtherTalk & Apple Internet Router Problem (11/94)

Article Created: 10 January 1991

TOPIC -----

Macintosh IIci systems running the AppleTalk Internet Router and EtherTalk have been found to "freeze up" in certain high-traffic situations. What can I do?

DISCUSSION -----

The solution is to install EtherTalk on the Macintosh IIci using the Network Products Installer that was released with System 6.0.7. This installs a new version of the .ENET driver in the System file that resolves the problem.

Copyright 1991-94, Apple Computer, Inc.

Keywords: knts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 6623