## Tech Info Library

## Workgroup Server 8550: Drive Options (5/96)

Article Created: 16 May 1996
TOPIC
What are my options for adding additional drives to the Workgroup Server 8550? What is special about the bracket that is included in the full height bay at the bottom of the Computer?

The workgroup server 8550 has four bays for drives. All 8550s come with a CD-ROM in the top bay (bay number one), a Floppy drive in the bay beneath that (bay number two), and a Hard Drive in the bottom bay (bay number four). The third bay down can be filled with a DAT drive depending upon the configuration purchased.

The bottom bay (bay number four) is a full height bay with part# 922-2253 mounted inside it. This mounting bracket has an additional fan to keep the drive(s) cool. Adding an additional half-height drive to this bracket does not require a mounting tray, only a screw kit to keep the drive secure.

Note: 922-2253 can be installed into an 8500 or an 8100.

## Begin\_Graphic

+-		-+
[	bay 1	]
[	CD-ROM	]
[		]
[	bay 2	]
[	Floppy	]
[		]
[	bay 3	]
[	Empty/DAT	]
[		]
[		]
[	bay 4	]
[	HD	]
[	with part#	]
[	922-2253	]
+		+

End\_Graphic

Copyright 1996, Apple Computer, Inc.

Keywords: cnfg

\_\_\_\_\_\_

This information is from the Apple Technical Information Library.

19960520 07:24:26.00

Tech Info Library Article Number: 19809