



# Tech Info Library

## Farallon StarController: IIGS and Iifx Upgrade Information

This article last reviewed: 10 July 1990

TOPIC -----

Is there a known problem using Macintosh IIfx systems with (older) Farallon's StarControllers similar to the problem with Apple IIGS systems on networks with StarControllers?

Do you have the date that StarControllers began shipping with the new PAL, and what is Farallon's policy regarding upgrading old controllers?

DISCUSSION -----

Farallon is aware of a performance loss when using the Macintosh IIfx and the Apple IIGS with the StarController, part number PN207. This occurs only on networks with Apple IIGS systems or Macintosh IIfx systems. Networks without these systems not experience any loss.

According to Farallon, the original StarController has been replaced with the PhoneNET StarController Series 300. The new product began shipping on April 30, 1990. Among other additions, this new version of the StarController contains the fix for the Apple IIGS and Macintosh IIfx.

For owners of the older StarController (PN207), chip upgrades (part number FX207) are available directly from Farallon. For more information, call Farallon customer service.

Copyright 1990 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 5939