



Tech Info Library

System 7: 64K Buffer RAM on Farallon Card for AppleShare Server

Article Created: 7 December 1992

TOPIC -----

My AppleShare server is responding very slowly since installing the Farallon Ethernet card. It's a System 7 compatible card and has System 7 compatible driver software. I sometimes experience temporary network disconnects.

DISCUSSION -----

Farallon Ethernet-equipped Macintosh computers that get heavy network traffic like AppleShare file servers require additional buffer RAM on the Farallon Ethernet card. Most Farallon Ethernet cards ship with 16K of buffer RAM. But 64K is recommended if the network traffic is high. You can obtain the additional RAM from Farallon.

To locate a vendor's address and phone numbers, use the vendor name as a search string.

Copyright 1992, Apple Computer, Inc.

Keywords: SYS7

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10978