



Tech Info Library

Macintosh: Connecting to an IBM 3090 with a ITT Courier 9440

This article last reviewed: 23 January 1990

TOPIC -----

At work, they are replacing an ITT Courier 9212 terminal (connected with coax cable) with the Macintosh using a channel-attached ITT Courier 9440 "Local Controller" (some kind of cluster controller).

Do you have any idea what this ITT Courier 9440 is? Is it a direct replacement for a 3274 cluster controller? Does the ITT Courier 9212 emulate a 3270 terminal? Is this going to work with the Macintosh?

DISCUSSION -----

The ITT Courier 9440 is a 3274-A/41-A channel-attached controller. The ITT Courier 9212 does emulate a 3270 terminal. Therefore, you can substitute the Courier 9212 with a Macintosh running MacTerminal and an IrmaLine from DCA. For more details, search the Technical Info library under "DCA".
Copyright 1990 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 5063