



Tech Info Library

Macintosh Continuously Reboots Itself

Article Created: 22 April 1986

Article Last Reviewed: 17 July 1992

Article Last Updated:

PROBLEM DESCRIPTION: After being powered on the Macintosh continuously reboots of its own initiative. During this process, it beeps about twice a second.

CAUSE: The power supply may be defective.

IMPORTANT: To avoid damage to Macintosh modules follow the instructions exactly as given in the "CURE:" below.

- CURE:**
1. Replace the power supply.
 2. Turn on the Macintosh and make all Level I adjustments.
 3. Run MacTest. If the problem remains, replace the Main Logic PCB.
 4. If the problem remains after step 3, replace the drive.

If the above cure doesn't fix the problem, search on GTS and the product's name to obtain a general troubleshooting procedure.
Copyright 1988, Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1899