



# Tech Info Library

## Macintosh LC, IIsi: Keys Take Place of Programmer's Switch

Article Created: 16 October 1990  
Article Last Reviewed: 15 July 1992  
Article Last Updated: 14 March 1991

### TOPIC -----

This article gives the keystroke combination that takes the place of the programmer's switch on the Macintosh LC and Macintosh IIsi.

### DISCUSSION -----

The Macintosh LC and Macintosh IIsi do not have a programmer's switch. Here are the key combinations for the Reset and non-maskable interrupt (NMI) functions:

- Control-Command-Power generates a reset.
- Command-Power generates an NMI.

Note: MacsBug 6.2b1 or later (available from APDA) needs to be installed for the non-maskable interrupt to happen when the Command and Power keys are pressed.

These key combinations are similar to those used in the Apple IIGS.  
Copyright 1990, 1991, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 6173