



Tech Info Library

Apple Scanner: Unable To Be Recognized Problem

This article last reviewed: 9 January 1990

TOPIC -----

I have had several problems with a Macintoshes SE/30 and my Apple Scanner.

When the Macintosh SE/30 is connected to the Apple Scanner, it doesn't recognize the scanner. The scanner does, however, work with a Macintosh IIX using the same cables and terminator.

I was finally able to make the connection between the Macintosh SE/30 and the scanner by putting a new hard drive in the SE/30, but I still don't know what the problem is.

DISCUSSION -----

You have a problem with impedance matching.

This is a known problem with the Apple Scanner. The situation occurs when the impedance created by a combination of devices and terminators on the SCSI chain causes one device to be "lost" on the chain.

There is no official service procedure. A workaround is to change the impedance of the SCSI chain by adding one or more terminators, SCSI devices, or an additional SCSI extender cable. The device in question should reappear.
Copyright 1990 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 5031