



# Tech Info Library

## ImageWriter II: SheetFeeder Causes Top/Bottom Margin Problems

This article last reviewed: 10 March 1988

PROBLEM DESCRIPTION: The ImageWriter II SheetFeeder pulls the paper in about a 1/4" too much. The end result is a document that has a 1.25" margin at the top and a .25" margin at the bottom.

CAUSE: DIP switch set incorrectly

CURE: 1. Switch 5 on the ImageWriter II should be set to open.  
Copyright 1988 Apple Computer, Inc.

Keywords: hts

-----  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1826