



Tech Info Library

LaserWriter Indicates A Paper Jam

This article last reviewed: 20 July 1988

PROBLEM DESCRIPTION: The LaserWriter I/O Board has been removed for troubleshooting purposes. The LaserWriter is powered on and the green light blinks. The LaserWriter then tries to generate a test print (as if the I/O board was still installed). After a short time the LaserWriter indicates that a paper jam exists when, in fact, there is no paper jam.

CURE: Remove and replace the scanner unit. Review the LaserWriter General Troubleshooting Procedures if the LaserWriter still indicates a paper jam.

Copyright 1988 Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 143