



Tech Info Library

Lisa 2: Possible Problems With The Upgrade Kit

This article last reviewed: 9 November 1988

1. Symptom: Operating system error 10726, or error 82.
Problem: Bad motherboard-ProFile interaction.
Solutions:
 - A. Replace the motherboard with an upgraded one. (Upgraded motherboards are distinguished by resistor packs around the parallel port.) Also make sure that the system has an I/O board with the resistors clipped and the proper boot ROMs installed.
 - B. Use a different ProFile.
2. Symptom: CPU boot error 43.
Problem: Bad CPU-boot ROM interaction.
Solutions:
 - A. Replace CPU board with upgraded CPU board.
 - B. Use the original Lisa boot ROMs. The only noticeable differences between using the old (version D) boot ROMs and using later revisions are (a) slightly different icons displayed in the Startup Menu, and (b) an apparent option to boot from two drives, though only one drive exists. Careful, though! If you select the top drive, the system hangs and must be reset.
3. Symptom: Blank screen when attempting to boot system after retrofitting.
Problem: Incorrectly labelled or placed CPU ROMs.
Solution:

Verify that the CPU ROMs are installed according to the directions. If they are correctly installed, one or both may be mislabelled. In that case, simply use the old version D boot ROMs instead.
4. Symptom: System goes through self-test, then hangs.
Problem: System is trying to start from nonexistent drive
Solutions:
 - A. If you're using your old CPU ROM:
Reset the system and tell it specifically what drive to boot from.
Preference settings, such as the correct time and the default startup

device, may have been lost when you unplugged the sytem to swap the chips. Since Preference's startup default is drive 1 with the old CPU ROMs, the system probably hung while booting, since (of couse) there is no drive 1.

B. If you have the new CPU ROMs installed:

- a. Reinstall the software.
- b. Test the memory boards with LisaTest or the extended memory board test.
- c. Test the memory board #2 by swapping it with with memory board #1 or with one from your spares kit.

Copyright 1988 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 469