



# Tech Info Library

## Apple Shared Library Manager: Errors And Resolution (3/95)

Article Created: 22 April 1994

Article Reviewed/Updated: 15 March 1995

TOPIC -----

Earlier revisions of the Apple Shared Library Manager may cause problems with the AV enabler or with the GeoPort on AV or Power Macintosh computers.

DISCUSSION -----

The Shared Library Manager extension and System Enabler 088 v1.0 are not compatible and may cause bus errors at startup. Both the QuickTake and GeoPort software install the Shared Library Manager extension. The Shared Library Manager makes the Macintosh operating system more efficient for developers.

System Enabler 088 v1.1 is compatible with the Shared Library Manager and fixes the bus error that may occur with version 1.0 of the System Enabler. An upgrade to the Shared Library Manager, to 1.1.2 or later, will resolve the problems also.

### Article Change History:

15 Mar 1995 - Corrected name of product in title.

08 Jul 1994 - Added info on the 1.1.2 version of the ASLM to resolve problems, retitled to more accurately reflect the contents of the article.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15197