



Tech Info Library

Apple IIe Card Software v2.0: Not Tested with System 6.0.7

Article Created: 16 September 1991

Article Last Reviewed: 3 June 1992

Article Last Updated:

TOPIC -----

Is it essential to install system software version 6.0.8 (that is, 7.0 print drivers) with the Apple IIe Card software version 2.0?

DISCUSSION -----

The Apple IIe software v2.0 was only tested using system software version 6.0.8. There is no known reason for the Apple IIe Card v2.0 software to fail using version 6.0.7. However, Apple cannot stand behind the use of version 6.0.7 due to the lack of testing.

Whatever configuration you decide on, the print driver versions must be the same on all systems. Otherwise, there will be driver conflicts when the printers are used.

Copyright 1991, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8874