



Tech Info Library

Apple IIe Card: A/ROSE Causing Error Running IIe Startup (1/95)

Article Created: 9 February 1993

Article Reviewed/Updated: 5 January 1995

TOPIC -----

Some customers launching the IIe Startup application are getting dialog to the effect "This card is defective." They may also be experiencing their IIe software "freezing" either while in use or after sitting idle. This can happen on any Macintosh computer that supports the Apple IIe Card.

This can also happen if you install an Apple Ethernet Card in certain Macintosh computers, and then later remove it and install in its place an Apple IIe Card. You may also encounter occasional crashes after approximately 30 minutes of idle time.

DISCUSSION -----

To correct this problem, delete the A/Rose and IIe Prefs files then restart. A/Rose is located in the Extensions Folder and IIe Prefs is located in the same folder as the IIe Startup application.

Article Change History:

04 Jan 1995 - Rewrote article to better explain the problem.

12 Oct 1994 - Combined two articles and generalized the information.

07 Dec 1993 - Added Perfoma information.

Support Information Services

Copyright 1993-95, Apple Computer, Inc.

Keywords: kcompat

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11362