



Tech Info Library

Macintosh II: Cure For Vertical Green Lines at Bottom of Screen

Article Created: 12 May 1988

Article Last Reviewed: 30 June 1992

Article Last Updated:

TOPIC -----

I have a problem that occurs on a Macintosh II with a color monitor and a video expansion card: Vertical green lines appear on the lower third of the screen when you select the 256-bit mode from the control panel. However, when in the 16-bit mode, the monitor behaves normally.

DISCUSSION -----

The problem may be a video RAM problem. Try replacing the eight extended video RAM chips with known, good video RAM. If the problem persists, you may need to replace a defective video card.

Copyright 1988 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2904