



Tech Info Library

Macintosh IIfx: Logic Board Jumper Settings

Article Created: 1 May 1991

Article Last Reviewed: 14 July 1992

Article Last Updated:

TOPIC -----

A customer's Macintosh IIfx is not functioning, and I suspect that the jumper settings on the logic board have been altered. What should I check for?

DISCUSSION -----

Jumper J103 on the Macintosh IIfx logic board disables the external 68030 RAM cache when it is disconnected. In the event that the jumper is removed, the system may not reset properly when turned on, essentially disabling the system.

As a side note, the jumper next to J103, J106, is used for debugging. This jumper is not documented because it can severely affect system performance.

Copyright 1991, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7446