



Tech Info Library

Macintosh IIsi: NuBus Card Shouldn't Touch Internal Hard Drive

Article Created: 14 June 1991

Article Last Reviewed: 17 July 1992

Article Last Updated:

TOPIC -----

In a Macintosh IIsi, the adapter board makes a 90 degree turn so a NuBus card can be parallel to the motherboard. Is a NuBus card supposed to actually touch the internal hard drive?

DISCUSSION -----

The NuBus card rests just above the hard drive. There is about 1/2-inch clearance between the drive and the NuBus card depending on the card type. The card doesn't rest on the hard drive.

Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8510