

Macintosh II: DIP- And Surface-Mounted SIMMs Are Equivalent

Article Created: 10 November 1988 Article Last Reviewed: 21 July 1992 Article Last Updated:
TOPIC
Can both DIP-mounted and surface-mounted SIMMs be used together in a Macintosh II with HD40 SC and 4MB RAM? Are all Macintosh II computers with HD40 SC and 4MB RAM supplied with DIP-mounted SIMMs?
DISCUSSION
There is no problem mixing DIP-mounted and regular surface-mounted SIMMs in the same computer. To the computer, they are the same. Macintosh II computers with HD40 SC and 4MB RAM may be supplied with either DIP-mounted SIMMs or surface-mount SIMMs. Copyright 1988 Apple Computer, Inc.
Keywords: <none></none>
This information is from the Apple Technical Information Library.
19960215 11:05:19.00

Tech Info Library Article Number: 3448