



Tech Info Library

Macintosh 512e: Not Enough Memory For HP Laserjet

Article Created: 14 May 1991

Article Last Reviewed: 29 May 1991

Article Last Updated:

TOPIC -----

I want to interface my Macintosh 512e with an HP Laserjet II. Is there a cable I can use?

DISCUSSION -----

We suspect that this can't be done due to memory constraints -- the drivers necessary to run the Laserjet require more than the 512e's 512K of RAM.

We would recommend that you contact the printer manufacturers for further information and a possible workaround for the memory issue.

For more information, search under: "Hewlett-Packard"

Copyright 1991, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8222