



Tech Info Library

Macintosh 630 family: Adding an Internal CD-ROM Drive (8/94)

Article Created: 05 August 1994

TOPIC -----

I ordered a Macintosh 630 family computer without an internal CD-ROM drive and now want to add one. What is the part number for the drive?

DISCUSSION -----

There are two options for adding an internal CD-ROM drive to a 630 family machine.

- Order the LC 550/575 kit, part number B1551LL/A, and don't use the faceplate for the 550/575. Inside the cover of the 630, the door over the CD can be popped out with two squeeze clips.
- A specific upgrade for the 630 family will be available in the near future. Waiting for that kit is the other option.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15995