



Tech Info Library

Macintosh 630 family: Internal Termination Specifics (11/94)

Article Created: 30 November 1994

TOPIC -----

I noticed that there are no terminating resistors on the internal SCSI devices in a Macintosh 630 family computer. How is termination handled?

DISCUSSION -----

The Macintosh 630 family has termination very near the SCSI connector on the logic board so no internal device requires termination. When adding an internal SCSI device, make sure it is free of terminating resistors. When removing an internal device, no termination concerns apply.

The existing SCSI termination rules still apply for external devices; terminate the last device in the chain.

The following computers are in the Macintosh 630 family: Performa 630, Performa 635, Performa 636, Performa 637, Performa 638, LC 630, and Quadra 630.

Support Information Services
Copyright 1994, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16820