



Tech Info Library

Macintosh 630 Series Computers and SCSI Manager 4.3.1 (6/95)

Article Created: 6 June 1995

TOPIC -----

Customers who have a Macintosh LC 630, Quadra 630, Performa 630 series computers and are performing large transfers of data to an external SCSI drive will need to install the "630 SCSI Update" extension in order to alleviate a potential system error from occurring. The 630 SCSI Update is available from online services, and the Internet. Do I still need this update after installing System 7.5 Update 1.0?

DISCUSSION -----

The 630 SCSI Update was rolled into SCSI Manager 4.3.1 which is installed as part of System 7.5 Update 1.0. The installer for System 7.5 Update 1.0 will remove the 630 SCSI Update extension but will fail to install the SCSI Manager 4.3.1 extension unless a custom install is performed. A user must perform this custom installation by:

- 1) Double Clicking on Install System 7.5 Update document.
- 2) Click the Continue... button at the information screen.
- 3) Select the Custom Install command from the pop-up menu in the upper left portion of the Install window.
- 4) Scroll down to Extensions in the list of features to install and click on the triangle to the left, a sub listing will appear underneath.
- 5) Locate SCSI Manager in this list and click the checkbox to the left to select it.
- 6) Click the Install button and follow the instructions.

This will install the SCSI Manager 4.3.1 extension into the extensions folder located in the System folder.

Keywords: supt

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17885