



Tech Info Library

Macintosh 630 LC: Sound From Comm Slot Express Modem (6/95)

Article Created: 19 June 1995

TOPIC -----

I have a Macintosh 630 LC with a Communications Slot Express Modem Card. How can I hear the modem during dialing or during the handshaking process?

DISCUSSION -----

There was a bug in the original Macintosh 630 LC that prevented the Communications Slot Express Modem's sound from playing through the speaker. This bug was fixed by the EM Sound Update 1.0 extension which has been incorporated into System Software 7.5 Update 1.0. If you install System 7.5 and System 7.5 Update 1.0 there is no longer a need for the EM Sound Update.

These articles can help you locate the software update mentioned here:

- "Where To Find Apple Software Updates" -- Lists online services for free Apple software updates.
- "Obtaining Apple Product Support in the USA" -- Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech Info Library.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: ksts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17976