



# Tech Info Library

## Macintosh LC II: Not Capable of Running A/UX

Article Created: 23 March 1992

Article Last Reviewed:

Article Last Updated:

TOPIC -----

Can the Macintosh LC II run A/UX 3.0?

DISCUSSION -----

No, the Macintosh LC II cannot run A/UX, which puts heavier demands on hardware resources than the Macintosh operating system does.

The Macintosh LC II is not a suitable A/UX platform for the following reasons:

- The Macintosh LC II lacks an FPU.
- It has limited RAM expansion and internal hard disk space.
- It has a 16-bit data path.

Copyright 1992, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 9951