



# Tech Info Library

## Macintosh LC II: Why No Two-Floppy Configuration

Article Created: 23 March 1992

Article Last Reviewed:

Article Last Updated:

TOPIC -----

Why is a two floppy drive configuration not offered on Macintosh LC II?

DISCUSSION -----

The second floppy drive was removed to save cost and space on the logic board. In addition, the two-floppy configuration is an undesirable System 7 platform.

Copyright 1992, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 9956